| DTC | P0171 | System too Lean (Fuel Trim) |
|-----|-------|-----------------------------|
| DTC | P0172 | System too Rich (Fuel Trim) |

CIRCUIT DESCRIPTION

Fuel trim refers to the feedback compensation value compared against the basic injection time. Fuel trim includes short-term fuel trim and long-term fuel trim.

Short-term fuel trim is the short-term fuel compensation used to maintain the air-fuel ratio at its ideal theoretical value. The signal from the heated oxygen sensor indicates whether the air-fuel ratio is RICH or LEAN compared to the ideal theoretical value, triggering a reduction in fuel volume if the air-fuel ratio is rich, and an increase in fuel volume if it is lean.

Long-term fuel trim is overall fuel compensation carried out long-term to compensate for continual deviation of the short-term fuel trim form the central value due to individual engine differences, wear over time and changes in the usage environment.

If both the short-term fuel trim and long-term fuel trim are LEAN or RICH beyond a certain value, it is detected as a malfunction and the MIL lights up.

| DTC No. | DTC Detecting Condition | Trouble Area |
|---------|---|--|
| P0171 | When the air fuel ratio feedback is stable after engine warming up, the fuel trim is considerably in error on the RICH side. (2 trip detection logic) | Air intake (hose loose) Fuel line pressure Injector blockage Heated oxygen sensor (bank1 sensor1) malfunction Mass air flow meter Engine coolant temp. sensor |
| P0172 | When the air fuel ratio feedback is stable after engine warming up, the fuel trim is considerably in error on the LEAN side. (2 trip detection logic) | Fuel line pressure Injector leak, blockage Heated oxygen sensor (bank1 sensor1) malfunction Mass air flow meter Engine coolant temp. sensor |

HINT:

- When DTC P0171 is recorded, the actual air-fuel ratio is on the LEAN side. When DTC P0172 is recorded, the actual air-fuel ratio is on the RICH side.
- If the vehicle runs out of fuel, the air-fuel ratio is LEAN and DTC P0171 is recorded. The MIL then comes on.
- If the total of the short-term fuel trim value and long-term fuel trim value is within \pm 25 %, the system is functioning normally.

INSPECTION PROCEDURE

1 Check air induction system (See page SF-1).

NG Repair or replace

OK

2

Check for heated oxygen sensor data.

PREPARATION:

- Connect the OBD II scan tool or TOYOTA hand-held tester to the DLC3.
- (b) Warm up engine to normal operating temp.

CHECK:

Read the heated oxygen sensor output voltage and short-term fuel trim.

RESULT:

| Pattern | Heated oxygen sensor output voltage | Short-term fuel trim |
|---------|--|-------------------------|
| 1 | Lean condition (Changes at 0.55 V or less) | Changes at about + 20 % |
| 2 | RIch condition (Changes at 0.35 V or more) | Changes at about - 20 % |
| 3 | Except 1 and 2 | Except 1 and 2 |

3

Check for heated oxygen sensor (See page DI-203).

1, 2

3 Check fuel pressure (See page SF-5).

NG

Check and repair fuel pump, pressure regulator, fuel pipe line and filter (See page SF-5).

OK

Check injector injection (See page SF-20). 4

NG

Replace injector.

OK

Check mass air flow meter and engine coolant temp. sensor 5 (See page DI-180, DI-189).

NG

Repair or replace.

OK

6 Check for spark and ignition (See page IG-1).

NG

Repair or replace.

οк

Check and replace ECM (See page IN-25).